

CEN25LA377

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane left side (Courtesy of FAA)




Photograph 2 - Airplane right side (Courtesy of FAA)



Photograph 3 - Right wing damage (Courtesy of FAA)



Photograph 4 - Aft right wing damage (Courtesy of FAA)



Photograph 5 - Left wing fuel (Courtesy of FAA)