

CEN25LA381

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the front of the helicopter at the heliport (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the left side of the helicopter at the heliport (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the rear of the helicopter at the heliport (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the right side of the helicopter at the heliport (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the underside of the fuselage at the heliport (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the substantial damage sustained to the front left underside of the fuselage inside of a hangar (courtesy of Bell)



Photograph 7 - View of the substantial damage sustained to the rear right underside of the fuselage inside of a hangar (courtesy of Bell)