

CEN25LA394

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the underside of the fuselage inside of a hangar (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the underside of the fuselage inside of a hangar (courtesy of the Federal Aviation Administration)