

CEN25LA401

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the top of the inverted airplane in trees (courtesy of the Manistee County Sheriff's Office)




Photograph 2 - View of the left side of the inverted airplane in trees (courtesy of the Manistee County Sheriff's Office)



Photograph 3 - View of both of wings and both wing struts (courtesy of the Federal Aviation Administration)




Photograph 4 - View of the left wing and the left wing strut (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the right wing and the right wing strut (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the broken ring terminal in the red circle (courtesy of the pilot)



Photograph 7 - View of the Garmin G3X unit voltage settings (courtesy of the pilot)



Photograph 8 - View of the backup ignition battery (courtesy of the pilot)