

National Transportation Safety Board

Office of Aviation Safety
Central Region



CEN25LA404

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front right of airplane at the accident site (Courtesy of Airplane Operator)



Photograph 2 - Front left of airplane at the accident site (Courtesy of Airplane Operator)



Photograph 3 - Airplane aft fuselage damage (Courtesy of Airplane Operator)