

CEN26LA013

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Airplane after being turned upright (Courtesy of Pilot)



Photograph 2 - Right side of Airplane after being turned upright (Courtesy of Pilot)