

CEN26LA035

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the right side of the airplane (courtesy of the pilot)



Photograph 2 - View of the top of the right side horizontal stabilizer (courtesy of the pilot)



Photograph 3 - View of the bottom of the right side horizontal stabilizer (courtesy of the pilot)