


CEN26LA067

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Aircraft (Courtesy of the Pilot)



Photograph 2 - Accident Aircraft Rudder Damage (Courtesy of the Pilot)