

CEN26LA076

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Original parking location (Courtesy of FAA)



Photograph 2 - Airplane parking location viewed from accident site (Courtesy of FAA)



Photograph 3 - Landing gear tracks (Courtesy of FAA)



Photograph 4 - Accident site (Courtesy of FAA)



Photograph 5 - Accident site, airplane rear (Courtesy of FAA)



Photograph 6 - Airplane left side (Courtesy of FAA)



Photograph 7 - Throttle position (Courtesy of FAA)