


CEN26LA092


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the substantial damage sustained to the lower fuselage near the cockpit (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the substantial damage sustained to the lower fuselage near the cockpit (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the substantial damage sustained to the lower fuselage near the cockpit (courtesy of the Federal Aviation Administration)