

CEN26LA101

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Downed Powerline (Courtesy of FAA)



Photograph 2 - Main Rotor System (Courtesy of FAA)



Photograph 3 - Right Landing Skid (Courtesy of FAA)



Photograph 4 - Location of Accident (Courtesy of FAA)