

CEN26LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of the accident site (courtesy of the Federal Aviation Administration)



Photograph 2 - View of the front of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 3 - View of the left side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 4 - View of the left wing at the accident site (courtesy of the Federal Aviation Administration)



Photograph 5 - View of the right side of the airplane at the accident site (courtesy of the Federal Aviation Administration)



Photograph 6 - View of the right wing at the accident site (courtesy of the Federal Aviation Administration)