

CEN26LA138

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Airplane (Courtesy of pilot)



Photograph 2 - Airplane Left wing damage (Courtesy of owner)



Photograph 3 - Airplane Vertical Stabilizer (Courtesy of pilot)



Photograph 4 - Airplane Right Wing (Courtesy of pilot)