

CEN26LA144

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of the front of the airplane at the accident site (courtesy of the Aero Valley Airport)**



**Photograph 2 - View of the left side of the airplane at the accident site (courtesy of the Aero Valley Airport)**



**Photograph 3 - View of the right side of the airplane at the accident site (courtesy of the Aero Valley Airport)**



**Photograph 4 - View of the fuel selector located on the left side cockpit floor (courtesy of the Federal Aviation Administration)**