

CEN26LA165

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Fuselage Damage Right side (Courtesy of FAA)



Photograph 2 - Fuselage Damage left side (Courtesy of FAA)



Photograph 3 - Amount of Collected fuel (Courtesy of FAA)