

CEN26LA177

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Ground scar and N422TW (Courtesy of pilot)



Photograph 2 - View of the rear empennage of N422TW (Courtesy of pilot)



Photograph 3 - View of runway 35 (Courtesy of Google Street View)