

CEN26LA182

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane (Courtesy of FAA)



Photograph 2 - Lower right wing (Courtesy of FAA)



Photograph 3 - Lower left wing (Courtesy of FAA)