

CEN26LA189

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Fire Dept.)



Photograph 2 - Airplane Damage (Courtesy of Fire Dept.)



Photograph 3 - Left Wing Fuel Check (Courtesy of Fire Dept.)



Photograph 4 - Left Wing Fuel Check (Courtesy of Fire Dept.)