

CEN26LA256

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N322TC damage path (Courtesy of Law Enforcement)



Photograph 2 - N322TC wreckage in corn field (Courtesy of Law Enforcement)