

CEN26LA272

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N2904R with left wing substantial damage (Courtesy of recovery company)



Photograph 2 - Left side fuselage damage at wing root (Courtesy of recovery company)