

CEN26LA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of Owner)



Photograph 2 - Accident Aircraft (Courtesy of Owner)



Photograph 3 - Accident site showing rudder on shoreline of pond (Courtesy of Owner)



Photograph 4 - Cockpit (Courtesy of Owner)