

DCA22LA182

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Runway Marks and Airplane at Rest (Courtesy FAA)



Photograph 2 - View of Runway Marks at Runway Edge (Courtesy FAA)



Photograph 3 - View of Runway Marks Looking Back (Courtesy FAA)



Photograph 4 - View of Damage to Flap Skin (Courtesy MHIRJ)



Photograph 5 - View of Nose Landing Gear (Courtesy MHIRJ)