

DCA22LA005

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Airplane at Rest After Event (Courtesy Air Wisconsin)



Photograph 2 - View of Tire Marks (Courtesy Air Wisconsin)



Photograph 3 -View of Tire Marks (Courtesy Air Wisconsin)



Photograph 4 - View of Damaged Sign (Courtesy Air Wisconsin)



Photograph 5 - View of Minor Damage to Left Wing (Courtesy Air Wisconsin)



Photograph 6 - View of Minor Damage to Left Wing (Courtesy Air Wisconsin)



Photograph 7 - View of Minor Damage to Left Wing Tip (Courtesy Air Wisconsin)



Photograph 8 - View of Airplane from Front (Courtesy Air Wisconsin)