

DCA24LA295


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wingtip of N808NW.



Photograph 2 - Left wingtip of N808NW.



Photograph 3 - Left wingtip of N808NW.



Photograph 4 - Right horizontal stabilizer of G-VPRD.



Photograph 5 - Right horizontal stabilizer of G-VPRD.



Photograph 6 - Right horizontal stabilizer of G-VPRD.



Photograph 7 - Right horizontal stabilizer of G-VPRD.