


DCA26LA142

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to the lower fuselage. See photograph 2 for the area highlighted in the orange box. (Courtesy of ANA)



**Photograph 2 - Damage to the lower fuselage between stations 1605 and 1719.
(Courtesy of ANA)**