



Photo 2: Main Wreckage (Far Background) with Area of Initial Tree Impact (Foreground), Looking Southeast. NTSB Digital Photo.