RECORD OF ☒ VISIT ☐ CONFERENCE OR ☐ TELEPHONE CALL

TIME: 08:00L

DATE: 03/29/2013

NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION
Thomas Kuhns, FAA ASI, SO-19

ROUTING

SYMBOL	INITIALS

SUBJECT
Inspection of in line fuel filter from N2549W accident.

DIGEST
The following information is in regard to the inspection of a transparent inline fuel filter removed from aircraft N2549W. This filter was located on a fuel line connected to the inlet side of the carburetor. There was no visible evidence of debris in the filter and overall appearance was normal.

CONCLUSION, ACTION TAKEN, OR REQUIRED
The fuel filter appears normal, unrestricted and free of debris.

DATE	TITLE	SIGNATURE
03/29/2013	Aviation Safety Inspector	[redacted]