



Photo 1: Digital Photograph Provided by FAA. View Depicting the Airplane at the Accident Site. Note the oil Pattern on the Vertical Stabilizer and the Displaced Engine/Engine Pylon.