



Photo 1 – Main Wreckage



Photo 2 - Fuel Control Panel



Photo 3 - Throttle Quadrant



Photo 4 - Right Propeller



Photo 5 - Close Up of Bent Blade on Right Propeller



Photo 6 - Left Propeller



Photo 7 - Fuel Control Cable Support Arm as Found In Main Tank Position



Photo 8 - Left Auxiliary and Main Shutoff Assembly Missing Control Cable



Photo 9 - Right Auxiliary and Main Shutoff Assembly Missing Control Cable



Photo 10 - Disconnected Right Fuel Valve Control Cable



Photo 11 - Disconnected Left Fuel Valve Control Cable