



Photo 1 – Broken Trees/Descent Path



Photo 2 – Broken Trees/Descent Path



Photo 3 – Initial Ground Impact Scar



Photo 4 – Downslope Just Beyond Initial Ground Impact Scar



Photo 5 – Wreckage Scatter



Photo 6 – Main Wreckage



Photo 7 – Main Wreckage



Photo 8 – Engine Power Panel



Photo 9 – Propeller Blades



Photo 10 - Engine