



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Close Up of Main Wreckage - Courtesy of FAA



Photo 3 – Location of Tire Marks on Runway 18



Photo 4 – Close Up of Tire Marks on Runway 18



Photo 5 – Tire Marks and Ground Scars on Left Side of Runway 18



Photo 6 – Ground Scars in Wheat Field



Photo 7 – Front View of Wreckage After Removal from Wheat Field



Photo 8 – Damage to Left Wing Tip



Photo 9 – Damage to Vertical Stabilizer and Rudder




Photo 10 – Broken Center Safety Belt Bracket



Photo 11 – Close Up of Broken Center Safety Belt Bracket