



**Photo 1 – Main Wreckage – Courtesy of FAA**



Photo 2 – Rotorcraft Data Plate – Courtesy of FAA





Photo 3 – Transmission Data Plate – Courtesy of FAA




**Photo 4 – Clutch Drum Housing – Courtesy of FAA**



**Photo 5 – Glazed Clutch Pads – Courtesy of FAA**



**Photo 6 – Close Up Photograph of Clutch Pad – Courtesy of FAA**



**Photo 7 – Clutch Drum Wear – Courtesy of FAA**