



Photo 1 – Digital Photograph Provided By Niagara County Sheriff's Office. View of the Airplane at the Accident Site.



Photo 2 - Digital Photograph Provided By FAA. Left Forward Quartering View of the Airplane after Recovery.



Photo 3 - Digital Photograph Provided By FAA. Right Forward Quartering View of the Airplane after Recovery.




Photo 4 - Digital Photograph Provided By FAA. View of the Propeller and Portion of the Engine. Note the fractured Propeller Blades.