



Photo 1 – Aft View of Airplane at Waterline (Courtesy FAA)



Photo 2 – Left Wing Leading Edge Damage (Courtesy FAA)



Photo 3 – Propeller Blade Bent Aft (Courtesy FAA)



Photo 4 – Airplane Secured to Trailer for Testing



Photo 5 – Engine Ready for Testing




Photo 6 – Engine Hoses