



Photo 1 – Overhead View of Airplane (Courtesy of FAA)



Photo 2 – View of Airplane During Recovery (Courtesy of FAA)



Photo 3 – View of Fuel Selector Position (Courtesy of FAA)



Photo 4 – View of Tachometer (Courtesy of FAA)



Photo 5 – Front View of Airplane After Recovery (Courtesy of FAA)



Photo 6 – View of Sealant in Left Wing Fuel Line