



Photo 1 – View of Engine (FAA)



Photo 2 – View of Empennage Damage (FAA)



Photo 3 – View of Auxiliary Tank (Atlanta Air Recovery)



Photo 4 – View of Fuel Selector (Atlanta Air Recovery)