



MEMORANDUM OF RECORD

Shawn Etcher
Air Safety Investigator
Eastern Region Aviation

September 25, 2014

Subject: ERA14LA450 – Still Photos Taken from FAA provided Video

The following photographs were extracted from an FAA video provided to the NTSB IIC.



Photo 1: Initial Impact Ground Scar



Photo 2: Right Side of Airplane - Post Recovery



Photo 3: Top right side and Tail of Airplane - Post Recovery



Photo 4: BRS Safety Pin in Place - Post Recovery



Photo 5: Hour meter indicating 0124.4 - Post Recovery