



Photo 1 – Aerial View of Accident Site Area (Provided by Flagler County Sheriff's Office)



Photo 2 - Aerial View 2 of Accident Site Area (Provided by Flagler County Sheriff's Office)



Photo 3 – View 1 of airplane as it came to rest



Photo 4 - View 2 of airplane as it came to rest



Photo 5 - View 3 of airplane as it came to rest



Photo 6 – View 1 of airplane after recovery (Provided by FAA)



Photo 7 - View 2 of airplane after recovery (Provided by FAA)



Photo 8 - View 3 of airplane after recovery (Provided by FAA)



Photo 9 - View 4 of airplane after recovery (Provided by FAA)



Photo 10 - View 5 of airplane after recovery (Provided by FAA)



Photo 11 - View 6 of airplane after recovery (Provided by FAA)



Photo 12 - View 1 of engine after recovery (Provided by FAA)



Photo 13 - View 2 of engine after recovery (Provided by FAA)



Photo 14 - Engine Disassembly View 1 (Provided by FAA)



Photo 15 - Engine Disassembly View 2 (Provided by FAA)



Photo 16 – View of Propeller after Recovery (Provided by FAA)