



Photo 1 – Recovered Wreckage




Photo 2 – Wreckage in Hangar



Photo 3 – Wreckage in Hangar



Photo 4 – Rotor Head



Photo 5 – Later-Recovered Tail Rotor and Drive Shaft (Courtesy FAA)



Photo 6 – Close-Up, Tail Rotor (Courtesy FAA)



Photo 7 - Close-Up, Tail Rotor (Courtesy FAA)