



Photo 1 – Right Side of Airplane at Rest (Courtesy Highland County Sheriff's Office)



Photo 2 – Bottom View of Airplane at Rest (Courtesy Highland County Sheriff's Office)



Photo 3 - Top View of Airplane at Rest (Courtesy Highland Country Sheriff's Office)




Photo 4 – Upper Channel Elevator Horn as Viewed




Photo 5 - Elevator Cable Clamp as Viewed




Photo 6 – Elevator Cable as Viewed



Photo 7 - Elevator Cable and Clamp as Viewed




Photo 8 - Hour Meter as Found