



**Photo 1 – NTSB Digital Photograph. View of the Impacted Building.**



**Photo 2 - NTSB Digital Photograph. View of the Separated Rudder with Rudder Trim Tab in the As-Found Location.**



**Photo 3 - Digital Photograph Taken by Fire Rescue. View Taken from Fire Rescue Ladder Depicting the Impacted Building.**



**Photo 4 - NTSB Digital Photograph. View Depicting the Rudder Torque Tube and Portion of Instrument Panel Inside Impacted Building.**




**Photo 5 - NTSB Digital Photograph. View of the Bag Found away from the Accident Site.**



**Photo 6 - NTSB Digital Photograph. View of the Recovered Propellers.**



**Photo 7 - NTSB Digital Photograph. View of the Tubular Structure From Fuselage Stations 91.25 to 168.5.**



**Photo 8 - Lycoming Digital Photograph. View of the Left Engine Assembly.**



**Photo 9 - Lycoming Digital Photograph. View of the Right Engine Assembly.**