



Photo 1 – NTSB Digital Photograph. View of the remains of the Wreckage at the Accident Site.



Photo 2 - NTSB Digital Photograph. View of the remains of the Left Wing



Photo 3 - NTSB Digital Photograph. View of the remains of the Right Wing



Photo 4 - NTSB Digital Photograph. View of the remains of the Empennage



Photo 5 - NTSB Digital Photograph. View of the Engine Assembly



Photo 6 - NTSB Digital Photograph. View of the Separated Propeller