



Photo 1 – Forward View of Accident Site



Photo 2 – View of Blade A (The White Blade) (Courtesy of Textron Aviation)



Photo 3 – View of Blade B (The Red Blade) (Courtesy of Textron Aviation)



Photo 4 – View of Main Rotor Blade Hub



Photo 5 – Aft View of Helicopter at Accident Site



Photo 6 – View of Tail Rotor



Photo 7 – Initial Impact Point Identified by Tree Strikes