



Photo 1 – Main Wreckage



Photo 2 – Close Up of Main Wreckage



Photo 3 – Propeller Blade



Photo 4 - Engine



Photo 5 – Right Side of Engine Showing Turbocharging System



Photo 6 – Turbocharger (Turbine Wheel and Turbine Wheel Housing)



Photo 7 – Close Up of Turbine Wheel



Photo 8 – No. 3 Piston



Photo 9 – Close Up of No. 3 Piston



Photo 10 – Fuel Selector Valve – Courtesy of Textron Aviation



Photo 11 – Upper Spark Plugs – Courtesy of Lycoming Engines



Photo 12 – Close Up of Upper Spark Plugs (No.1, No.3, and No.5) - Courtesy of Lycoming Engines



Photo 13 – Close Up of Upper Spark Plugs (No.2, No.4, and No.6) – Courtesy of Lycoming Engines



Photo 14 – Exhaust Bypass Valve (Wastegate) – Courtesy of Lycoming Engines



Photo 15 – Turbine Wheel After Removal from Turbine Housing



Photo 16 – Compressor Wheel after Removal of Remains of Compressor Housing



Photo 17 – Turbocharger Central Body Cavity – Courtesy of Hartzell Engine Technologies



Photo 18 – Oil Supply Line Check Valve – Courtesy of Hartzell Engine Technologies



Photo 19 – Turbine Wheel Assembly with Piston Ring – Courtesy of Hartzell Engine Technologies