



SCENE EXAMINATION REPORT

CSSS JOB NO. 1286

[illegible]

South Oyster Bay Rd

* NOTE - LIRR light bar - 20' 9" above pavement when aircraft came into contact. See photos, video and discription for further details of crash



Color Index

Pink - Right wing

Purple - Left wing

Green - Tail wings and section

Red - Cock pit and debris

Plane Crash

HOM 607-09, 215CR0329533

Weather: Clear

August 16, 2015

IO: DETBrezeski, HOM SQD

Condition : Dry

South Oyster Bay Rd and LIRR

Total Station: DET. Fleming, CSSS

See BEAST report for further details.