



Photo 1 – Severed Right Wing and Railroad Grade Crossing Cantilever Arm (NTSB Photo)



Photo 2 – Severed Right Wing (NTSB Photo)



Photo 3 – Severed Right Wing (NTSB Photo)



Photo 4 – Main Wreckage (NTSB Photo)



Photo 5 – Left Wing (NTSB Photo)



Photo 6 – Propeller Assembly (NTSB Photo)



Photo 7 – Forward Fuselage and Engine (NTSB Photo)



Photo 8 – Engine (NTSB Photo)



Photo 9 – Right Main Landing Gear and Forward Fuselage/Cockpit (NTSB Photo)



Photo 10 – Aft Fuselage and Empennage (NTSB Photo)



Photo 11 – Center Fuselage (NTSB Photo)



Photo 12 – Empennage (NTSB Photo)



Photo 13 – Left Wing (NTSB Photo)



Photo 14 – Forward Fuselage and Cockpit (NTSB Photo)



Photo 15 – Left Main Landing Gear (NTSB Photo)



Photo 16 – Right Main Landing Gear (NTSB Photo)



Photo 17 – Nose Landing Gear (NTSB Photo)