



Photo 1 – View of main wreckage.



Photo 2 – Front View of Engine.



Photo 3 – View of Damaged Propeller Blade.



Photo 4 – View of Right Wing and Empennage.