



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

May 11, 2017

PHOTO ARRAY

ERA15LA114



Photo 1 –Aircraft at Rest (Courtesy of the FAA)



Photo 2 – Nosewheel as found (Courtesy of the FAA)



Photo 3 – Impact Trail along Berm (Photo Courtesy of the FAA)



Photo 4 – Engine and Propeller as found (Courtesy of the FAA)