



Photo 1 – Airplane During Initial Climb (Courtesy of Eyewitness)



Photo 2 - Front View of Airplane at Rest (Courtesy of FAA)



Photo 3 – Left Aft View of Airplane at Rest (Courtesy of FAA)



Photo 4 – Gust Lock as Found (Courtesy of the FAA)




Photo 5 - Throttle and Mixture as Found (Courtesy of FAA)