



Photo 1 – View 1 of successive skid marks (Landowner)



Photo 2 – View 2 of successive skid marks (Landowner)



Photo 3 – View 3 of successive skid marks (Landowner)



Photo 4 – View 4 of successive skid marks (Landowner)



Photo 5 – View 5 of successive skid marks (Landowner)



Photo 6 – View of Airplane as Found (Landowner)



Photo 7 – View of airplane as found facing opposite direction of travel (Landowner)